

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ,
ਡੀ.ਏ.ਵੀ. ਪਬਲਿਕ ਸਕੂਲ,
ਸੁਨਾਮ।


ਨੰਬਰ: 37

ਮਿਤੀ: 30/04/2026

ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਪ੍ਰਾਪਤ ਹੋਇਆ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਦਾ ਕੇਸ ਸਬੰਧਿਤ ਜੇ.ਈ. ਵੱਲੋਂ ਮਿਤੀ: 22.04.2026 ਨੂੰ ਸਕੂਲ ਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਕੀਤੀ ਗਈ ਰਿਪੋਰਟ ਅਨੁਸਾਰ ਸਾਲ 2026-28 ਬਿਲਡਿੰਗ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਆਪ ਵੱਲੋਂ ਆਨਲਾਇਨ ਖਜਾਨੇ (Head of Account 8782-00-102-01-00) ਵਿੱਚ ਬਾਬਤ ਰੁਪਏ 30,000/- (ਤੀਹ ਹਜ਼ਾਰ ਰੁਪਏ ਸਿਰਫ) Receipt. No. 23147098 ਮਿਤੀ: 27.04.2026 ਰਾਹੀਂ ਜਮਾਂ ਕਰਵਾ ਦਿੱਤੀ ਗਈ ਹੈ।


ਨੋਟ:- ਸਰਟੀਫਿਕੇਟ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਸੰਗਰੂਰ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. ਸਪੈਸ਼ਲ-1 ਮਿਤੀ:20.04.2026 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾਂ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

Part-II


Building Safety Report

Name of School: DAV PUBLIC SCHOOL, SUNAM

Sh. SATNAM SINGH (Junior Engineer) has visited the above mentioned school on dated 22/04/2026 and on his visual inspection; the building seems to be safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) This Certificate holds validity with valid Fire Safety Certificate. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **Two Year, upto 31.03.2028**


(Satnam Singh)
J.E


Sub Divisional Engineer
Const. Sub Divn.No.2 PWD, B&R
Sangrur.