

## Part-II


### Building Safety Report

Name of School: D.A.V Public School, Sunam Distt. Sangrur.

I have visited the above-mentioned School Building along with Sh. Anil Kumar (Assistant Engineer) and on visually inspection; it seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **One Year, upto 31-03-2024**

  
VIJAY PRAKASH GUPTA  
PRINCIPAL  
DAV PUBLIC SCHOOL  
SUNAM (Sangrur) Pb.

  
Sub Divisional Engineer  
Const. Sub Divn.No.2 PWD, B&R  
Sangrur.

  
Dolly Roy  
Manager  
DAV Public School  
Sunam (Sangrur) Pb.

  
Anirudh Vashisht  
Chairman  
DAV Public School  
Sunam (Sangrur) Pb.